

Indoor Calibration Target



Jackson Pollock, *One: Number 31*, 1950

Instructions:

1. Print off this target. Color or black and white are both acceptable.
2. Point your sensor at the target. Move slowly, stopping to allow the sensor to gather more blue dots.



Structure